
TI 810-32 10 January 2002



NOTE: 2 HANDLES REQ'D, PER HINGED TOP, MIN. 6 PER PIT COVER ASSEMBLY.



Figure 3-12. Handle Detail.